

Work Order ID 151572

Tuesday, October 04, 2016 7:55:57 AM

151572

Page 1

Item ID: D3446-041

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Y Back

Start Date: 10/4/2016 Start Qty: 4.00

4

Cust Item ID:

Required Date: 10/6/2016 Req'd Qty: 4.00

4

Customer:

Reference: RA112376

Approvals: Process Plan: emDate: 16/10/04

Tooling:

Date: _____

Run Start

NR1

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D3446

Rev B

150

0.00

150

QC

Quality Control

Memo

INSPECT RA112376

4 X D3446-041

SCRAP/DESTROY AS PER INSTRUCTION SHEET

0.00

④ 16-10-07

Ø em 16/10/12.

DAS
9
9-89

Picklist Print

Page 1

Tuesday, October 04, 2016 7:55:56 AM

Work Order ID: 151572

151572

Parent Item: D3446-041

D3446-041

Parent Item Name: Y Back

Start Date: 10/4/2016

Required Date: 10/6/2016

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP A 05.09.01New issueKJ/JLM
IPP Rev:B As per Rev B 06-03-10 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3446-041		Manufactured	No				Each	0.0000		4			
D3446-041									**				

Y Back

Handwritten notes: DAS 9 9-89 16-10-07, U/A

List Lots

Page 1 of 1

Tuesday, October 04, 2016 7:37:21 AM

Criteria : Item ID: D3446-041 All Locations All Warehouses All Quantity

Item ID Item Name	Warehouse ID Location ID	Lot Number	Last Trans Date	Lot Qty	Shelf Life Dt	Lot Code	Type Code	Comments
D3446-041 Y Back	Main Warehouse Return2016	XXX	10/3/2016	4.0000				
Total:				4.0000				

Inspection Sheet Complete RA112376

Customer QA Ref #

0

Part Number	Batch / Serial #	Quantity	Part Complete	Rev/CHG Current	New Paperwork	New Labels	Disposition	Work order #	Work order instructions
D3446-041	TBA	4	☐ Yes	☐ Yes	☐ Yes	☐ Yes	DAMAGED/SCRAP	151572	belts return used and worn out labels. No traceability found
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			Did a system accept
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			

QC Approval: P.D. _____

Date: 29-Sep-16 _____

REORDER FROM:
AVIATION BUSINESS SYSTEMS
716 NORTH MEMORIAL PARKWAY
HUNTSVILLE, ALABAMA 35891

Maintenance Release

The aircraft, airframe, aircraft engine, propeller or appliance identified below was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repairs are on file at this repair station under work order # _____

Dated _____

Inspected By _____

Cert. # _____

Non-SERVICEABLE

Name Seat Belt Harness D3446-041

Unit T30-C154 / 044382-041

Aircraft Bell 212 ID# N316LH

Disposition Non serviceable

Reason For Removal Illegible Tags or Missing

Removed by [Signature] Date 8/16/16

Project Code: DAR08003 TS

MFG DATE: 06/08
FAA Certificate No.

REORDER FROM:
AVIATION BUSINESS SYSTEMS
716 NORTH MEMORIAL PARKWAY
HUNTSVILLE, ALABAMA 35891

Maintenance Release

The aircraft, airframe, aircraft engine, propeller or appliance identified below was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repairs are on file at this repair station under work order # _____

Dated _____

Inspected By _____

Cert. # _____

Non SERVICEABLE

Name Seat Belt Harness D3446-041

Unit T30-C154 / 044382-041

Aircraft Bell 212 ID# N316LH

Disposition Non Serviceable

Reason For Removal Illegible Tags or Missing

Removed by [Signature] Date 8/16/16

Project Code: DAR08003 TS

MFG DATE: 06/08
FAA Certificate No.

Maintenance Release

The aircraft, airframe, aircraft engine, propeller or appliance identified below was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repairs are on file at this repair station under work order # _____

Dated _____

Inspected By _____

Cert. # _____

NON - SERVICEABLE

Name Seat Belt Harness 446-041

Unit TSO-C114 / D4327-041

Aircraft Boeing 212 ID# N316LH

Disposition Non-serviceable

Reason For Removal Illegible tags or missing

Removed by W. H. H. H. Date 8/16/16

Project CODE: DAR08003 TS

MFR DATE: 06/08
FAA Certificate No.

Maintenance Release

The aircraft, airframe, aircraft engine, propeller or appliance identified below was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repairs are on file at this repair station under work order # _____

Dated _____

Inspected By _____

Cert. # _____

NON - SERVICEABLE

Name Seat Belt Harness

Unit TSO-C114 / D4327-041 D3446-041

Aircraft Boeing 212 ID# N316LH

Disposition Non-serviceable

Reason For Removal Illegible tags or missing

Removed by W. H. H. H. Date 8/16/16

Project CODE: DAR08003 TS

MFR DATE: 06/08
FAA Certificate No.